

<u>Preventive Maintenance – Spray Equipment Lathe With</u> <u>3-Axis</u>

| Preventive Action | Safety Inspection | Basic Service Contract | Upgraded Service Contract |
|----------------------------------|----------------------|------------------------------|---------------------------------|
| Service Interruption | Minimal | Medium | Full planned |
| Service interruption | IVIIIIIIIII | Medium | outage |
| | | | Outage |
| Headstock: | | | |
| Lubricate bearings | | Х | X |
| Check motors for spin speed | X | X | X |
| Check wear of pulleys and belt | | X | 7. |
| Replace pulleys and belt | | | Х |
| Chuck run out and adjust | | | X |
| Concentricity and adjust | | | X |
| Inspect dead center | X | Х | X |
| Inspect position of safety cover | X | X | X |
| Check RPM pickup | | Х | Х |
| Adjust gearbox oil level | | | Х |
| Tailstock: | | | |
| Check condition of live center | X | Χ | Х |
| Inspect air valve and cylinder | X | Х | Х |
| Inspect air regulator & gauge | X | Χ | X |
| Inspect air lines for leakage | X | Χ | Х |
| Add hydraulic pump oil | | | X |
| Check hydraulic cylinders | | X | Х |
| Check hydraulic lines | X | X | X |
| Check gauge for functionality | | Χ | Х |
| Inspect rollers and CAMS | X | Х | Х |
| Traverse (3 Axis): | | | |
| Check V-groove rollers | X | Х | X |
| Check anchor bolts | X | Χ | X |
| Check linear drives | X | X | X |
| Check gear rack and pinion | X | Х | X |
| Check flex chains and cables | X | Х | X |
| Check traverse play | X | Х | X |
| Check air lines | X | X | X |
| Check Servo motors and | X | Х | X |
| connections | | | |



<u>Preventative Maintenance – Spray Equipment Lathe With</u> <u>3-Axis</u>

| Preventive Action | Safety Inspection | Basic Service Contract | Upgraded Service Contract |
|---------------------------------|----------------------|------------------------------|---------------------------------|
| Service Interruption | Minimal | Medium | Full planned |
| | | | outage |
| | | | |
| Bed: | | | |
| Check centerline alignment | | Χ | X |
| Check top surface for tail stk. | Χ | X | X |
| Inspect leveling bolts | X | X | X |
| Inspect floor anchors | X | X | X |
| Control panel: | | | |
| Check safety circuits | | X | X |
| Clean VFD | | X | X |
| Clean cooling fan | | X | X |
| Check intake fan | Χ | X | Χ |
| Inspect RPM display | X | X | X |
| Check local & remote controls | | X | X |
| Inspect terminal tightness | | | X |
| Test incoming power | | X | Х |
| Test control power (VDC or VAC) | | Χ | Χ |
| Test amp draw for lathe | | Χ | Χ |
| Check remote pendant | X | X | X |

Note: Additional charges will apply if travel time to facility is greater than one hour from Arzell, Inc.